



HEIN | LEHMANN

GRUNDSTOFFSIEBE

**MASCHENWEITENLISTE
PS-GITTER FORM F**

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
8,0	5,0
10,0	5,0
	6,0
12,0	5,0
	6,0
13,0	5,0
	6,0
13,5	5,0
14,0	5,0
15,0	5,0
	6,0
	7,0
	8,0
16,0	5,0
	6,0
	7,0
	8,0
17,0	5,0
	6,0
	8,0
17,5	5,0
	6,0
18,0	5,0

MW mm	Draht Ø mm
	6,0
	7,0
	8,0
19,0	5,0
	6,0
	7,0
19,5	6,0
20,0	5,0
	6,0
	7,0
	8,0
	10,0
	20,0
21,0	10,0
22,0	5,0
	6,0
	7,0
	8,0
	10,0
23,0	5,0
	6,0
	7,0
	8,0

MW mm	Draht Ø mm
24,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
25,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
	15,0
26,0	6,0
	7,0
	8,0
	10,0
	12,0
27,0	7,0
	8,0
	10,0
	12,0
28,0	5,0

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
	6,0
	7,0
	8,0
	10,0
	12,0
29,0	5,0
	8,0
	10,0
	12,0
30,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
	15,0
31,0	6,0
	8,0
	10,0
	12,0
	15,0
32,0	5,0
	6,0

MW mm	Draht Ø mm
	7,0
	8,0
	10,0
	12,0
	15,0
33,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
33,5	7,0
	8,0
	10,0
34,0	6,0
	7,0
	8,0
	10,0
	12,0
35,0	5,0
	6,0
	7,0
	8,0

MW mm	Draht Ø mm
	10,0
	12,0
	15,0
36,0	8,0
	10,0
	12,0
37,0	5,0
	8,0
	10,0
37,5	8,0
38,0	5,0
	8,0
	10,0
	12,0
39,0	5,0
	7,0
	8,0
40,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0

*Andere bzw. Abweichende Ausführungen auf Anfrage.

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
	15,0
	20,0
41,0	5,0
	8,0
42,0	6,0
	8,0
	10,0
	12,0
43,0	5,0
	8,0
	10,0
43,5	15,0
44,0	6,0
	15,0
44,5	5,0
45,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
	15,0
	20,0

MW mm	Draht Ø mm
46,0	6,0
	8,0
	10,0
	15,0
47,0	5,0
	8,0
	10,0
48,0	6,0
	7,0
	8,0
	10,0
	12,0
	15,0
49,0	5,0
50,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
51,0	5,0
	6,0

MW mm	Draht Ø mm
	10,0
	12,0
52,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
53,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
54,0	6,0
	8,0
	10,0
	12,0
55,0	5,0
	7,0
	8,0
	10,0
	12,0

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
	15,0
	20,0
56,0	6,0
	10,0
	12,0
	15,0
	20,0
57,0	5,0
	7,0
	8,0
	15,0
58,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
59,0	5,0
	7,0
60,0	6,0
	7,0
	8,0
	10,0

MW mm	Draht Ø mm
	12,0
	15,0
	20,0
61,0	5,0
	7,0
	8,0
62,0	6,0
	7,0
	8,0
	10,0
	12,0
63,0	5,0
	7,0
	8,0
	10,0
	12,0
	15,0
64,0	5,0
	6,0
	8,0
	10,0
	12,0
65,0	5,0

MW mm	Draht Ø mm
	6,0
	7,0
	8,0
	10,0
	12,0
	15,0
	20,0
66,0	6,0
	8,0
	10,0
	12,0
67,0	5,0
	7,0
	8,0
	12,0
	15,0
	20,0
68,0	6,0
	8,0
	10,0
	12,0
	15,0
69,0	5,0

*Andere bzw. Abweichende Ausführungen auf Anfrage.

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
	6,0
	7,0
	15,0
70,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
71,0	5,0
	7,0
	10,0
	12,0
	15,0
72,0	6,0
	8,0
	10,0
	12,0
	20,0
73,0	5,0
	7,0
	8,0

MW mm	Draht Ø mm
	15,0
74,0	6,0
	7,0
	8,0
	10,0
	12,0
75,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
	15,0
76,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
77,0	5,0
	7,0
	10,0
	15,0

MW mm	Draht Ø mm
78,0	6,0
	8,0
	10,0
	12,0
80,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
81,0	5,0
	7,0
	15,0
82,0	5,0
	6,0
	8,0
	10,0
	12,0
83,0	5,0
	7,0
	10,0
	15,0

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
84,0	6,0
	7,0
	8,0
	10,0
	12,0
	20,0
85,0	5,0
	7,0
	8,0
	10,0
	12,0
	15,0
86,0	20,0
	6,0
	7,0
	8,0
	10,0
	12,0
87,0	5,0
	6,0
	7,0
	15,0
88,0	5,0

MW mm	Draht Ø mm
90,0	6,0
	8,0
	10,0
	12,0
	5,0
	6,0
91,0	8,0
	10,0
	12,0
	15,0
	20,0
	5,0
92,0	7,0
	8,0
	15,0
	7,0
	8,0
	10,0
93,0	12,0
	5,0
	6,0
	7,0
	12,0

MW mm	Draht Ø mm
94,0	15,0
	5,0
	6,0
	8,0
	10,0
	12,0
95,0	5,0
	7,0
	10,0
	12,0
	15,0
	20,0
96,0	6,0
	8,0
	10,0
	12,0
	5,0
	7,0
97,0	8,0
	15,0
	6,0
	7,0
98,0	8,0
	6,0
	7,0
	8,0

*Andere bzw. Abweichende Ausführungen auf Anfrage.

MASCHENWEITENLISTE

PS-GITTER FORM F

MW mm	Draht Ø mm
	10,0
	12,0
100,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
105,0	5,0
	6,0
	7,0
	15,0
	20,0
110,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
114,0	20,0
115,0	5,0

MW mm	Draht Ø mm
	8,0
	15,0
	20,0
120,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
125,0	5,0
	7,0
	10,0
	15,0
130,0	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
135,0	5,0
	6,0

MW mm	Draht Ø mm
	8,0
	15,0
140,0	5,0
	8,0
	10,0
	12,0
	20,0
145,0	5,0
	7,0
150,0	15,0
	5,0
	6,0
	8,0
	10,0
	12,0
	15,0
	20,0
155,0	5,0
	15,0