



**HEIN | LEHMANN**

# **GRUNDSTOFFSIEBE**

**MASCHENWEITENLISTE  
DOVEX-R-GITTER FORM E**

# MASCHENWEITENLISTE

## DOVEX-R-GITTER FORM E

MW mm	Draht Ø mm
3,2	1,6
4,0	1,6
5,0	2,0
6,0	1,6
6,3	2,5
8,0	2,8
10,0	2,0
	3,0
	3,5
12,0	4,0
	5,0
12,5	3,0
13,0	4,0
	5,0
14,0	4,0
	5,0
15,0	4,0
	5,0
	6,0
16,0	4,0
	5,0
	6,0
17,0	5,0

MW mm	Draht Ø mm
	6,0
18,0	5,0
	6,0
19,0	5,0
	6,0
	7,0
20,0	5,0
	6,0
	7,0
21,0	5,0
	6,0
	7,0
22,0	5,0
	6,0
	7,0
23,0	5,0
	6,0
	7,0
	8,0
24,0	5,0
	6,0
	7,0
	8,0

MW mm	Draht Ø mm
25,0	5,0
	6,0
	7,0
	8,0
	10,0
26,0	5,0
	6,0
	7,0
	8,0
	10,0
27,0	5,0
	6,0
	7,0
	8,0
	10,0
28,0	5,0
	6,0
	7,0
	8,0
	10,0
29,0	5,0
	6,0
	7,0

# MASCHENWEITENLISTE

## DOVEX-R-GITTER FORM E

MW mm	Draht Ø mm
	8,0
	10,0
30,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
31,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
32,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
33,0	5,0
	6,0
	7,0

MW mm	Draht Ø mm
	8,0
	10,0
	12,0
34,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
35,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
36,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
37,0	5,0
	6,0

MW mm	Draht Ø mm
	7,0
	8,0
	10,0
	12,0
38,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
39,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
40,0	5,0
	6,0
	7,0
	8,0
	10,0
	12,0
41,0	5,0

# MASCHENWEITENLISTE

## DOVEX-R-GITTER FORM E

MW mm	Draht Ø mm
	6,0
	7,0
	8,0
	10,0
42,0	12,0
	6,0
	7,0
	8,0
	10,0
43,0	12,0
	6,0
	7,0
	8,0
	10,0
	12,0
44,0	6,0
	7,0
	8,0
	10,0
	12,0
45,0	6,0
	7,0
	8,0

MW mm	Draht Ø mm
	10,0
	12,0
46,0	6,0
	7,0
	8,0
	10,0
	12,0
47,0	6,0
	7,0
	8,0
	10,0
	12,0
48,0	6,0
	7,0
	8,0
	10,0
	12,0
49,0	6,0
	7,0
	8,0
	10,0
	12,0
50,0	6,0

MW mm	Draht Ø mm
	7,0
	8,0
	10,0
	12,0
51,0	7,0
	8,0
	10,0
	12,0
52,0	7,0
	8,0
	10,0
	12,0
53,0	7,0
	8,0
	10,0
	12,0
54,0	7,0
	8,0
	10,0
	12,0
55,0	7,0
	8,0
	10,0

\*Andere bzw. Abweichende Ausführungen auf Anfrage.

# MASCHENWEITENLISTE

## DOVEX-R-GITTER FORM E

MW mm	Draht Ø mm
	12,0
56,0	8,0
	10,0
	12,0
57,0	8,0
	10,0
	12,0
58,0	8,0
	10,0
	12,0
59,0	8,0
	10,0
	12,0
60,0	8,0
	10,0
	12,0
61,0	8,0
	10,0
	12,0
62,0	8,0
	10,0
	12,0
63,0	8,0

MW mm	Draht Ø mm
	10,0
	12,0
64,0	8,0
	10,0
	12,0
65,0	8,0
	10,0
	12,0
66,0	8,0
	10,0
	12,0
67,0	8,0
	10,0
	12,0
68,0	8,0
	10,0
	12,0
69,0	8,0
	10,0
	12,0
70,0	8,0
	10,0
	12,0

MW mm	Draht Ø mm
71,0	10,0
	12,0
72,0	10,0
	12,0
73,0	10,0
	12,0
74,0	10,0
	12,0
75,0	10,0
	12,0
76,0	10,0
	12,0
77,0	10,0
	12,0
78,0	10,0
	12,0
79,0	10,0
	12,0
80,0	10,0
	12,0
81,0	10,0
	12,0
82,0	10,0

# MASCHENWEITENLISTE

## DOVEX-R-GITTER FORM E

MW mm	Draht Ø mm
	12,0
83,0	10,0
	12,0
84,0	10,0
	12,0
85,0	10,0
	12,0
86,0	10,0
	12,0
87,0	10,0
	12,0
88,0	10,0
	12,0
89,0	10,0
	12,0
90,0	10,0
	12,0
91,0	10,0
	12,0
92,0	10,0
	12,0
93,0	10,0
	12,0

MW mm	Draht Ø mm
94,0	10,0
	12,0
95,0	10,0
	12,0
96,0	10,0
	12,0
97,0	10,0
	12,0
98,0	10,0
	12,0
99,0	10,0
	12,0
100,0	10,0
	12,0
101,0	12,0
102,0	12,0
103,0	12,0
104,0	12,0
105,0	12,0
106,0	12,0
107,0	12,0
108,0	12,0
109,0	12,0

MW mm	Draht Ø mm
110,0	12,0
111,0	12,0
112,0	12,0
113,0	12,0
114,0	12,0
115,0	12,0
116,0	12,0
117,0	12,0
118,0	12,0
119,0	12,0
120,0	12,0